



GARY R. HERBERT  
Governor  
GREGORY S. BELL  
Lieutenant Governor

# State of Utah


## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program October 12, 2011

Reviewed: 

<b>Mine Name:</b> Bromide Basin	<b>Permit Number:</b> S0170031
<b>Operator Name:</b> Bromide Mining LLC	<b>Inspection Date:</b> October 04, 2011
<b>Inspector(s):</b> Wayne Western	<b>Time:</b> 9:30 – 11:00 AM
<b>Other Participants:</b> John Reay (BLM), Shane Scott (Permittee)	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

This inspection was a follow up to an earlier inspection to inspect areas at the upper areas that were inaccessible in an earlier inspection..

#### Inspection Summary:

The Permittee is current with their fees. The bond amount is \$25,000 and is due for renewal on July 15, 2012.

The Permittee is conducting drilling operations within the permit boundaries. The inspection included the areas of active drill and the upper areas that were inaccessible in an earlier inspection. No drilling was conducted in the upper areas. The Division did not see any new disturbance in the upper areas. The weather conditions were such that most of the upper area was covered in fog (clouds). While visibility was limited there were no signs of drilling activity or new disturbance in the upper areas..

The Permittee had drilled exploration holes. All but one on the holes had been plugged. The unplugged hole had a stuck drill rod.

**Conclusions and Recommendations:**

**Inspector's Signature**

WHW:

cc: (OPERATOR)

Sue Fivecoat, BLM

John Reay, BLM

O:\M017-Garfield\S0170031-Bromidebasin\inspections\INSP-06052011.doc

A handwritten signature in blue ink, appearing to read "Wayne White", is written over a horizontal line.



Drill hole with stuck drill stem



Plugged drill holes